



## SERVICE BULLETIN 02-3401

Contact: Mike Hankins, Director of Customer Relations  
Mainship Corporation  
[mhankins@mainship.com](mailto:mhankins@mainship.com)

December 2, 2002

Models Affected: Pilot™34

Customer over cranking generator may allow water to be ingested into generator.

Any Pilot™34 with generator installed should be checked for installation of a scoop-type water pick up.

Any boats in the field that have a scoop type pick-up should have an anti-siphon installed to prevent water being backed up into generator.

Questions can be communicated to Mainship Engineering or Warranty/Service department.  
Thanks for your assistance.

Mike Hankins  
(904) 827-2025  
(800) 578-0852