



SERVICE BULLETIN 03-3904

Contact: Mike Hankins, Director of Customer Relations
Mainship Corporation
mhankins@mainship.com

March 26, 2003

Models Affected: Mainship 350 and 39 Trawlers

A number of owners of the Mainship 350 and 39 Trawler models have reported to Mainship that water has infiltrated into their swim platforms. An inspection of these swim platforms has revealed that in some cases, the infiltration has been minimal or nonexistent and, in others, substantial. While infiltration does not generally present a structural problem, it should be corrected. Accordingly, Mainship has established a procedure that will provide a method to 350 and 390 Trawler owners to determine whether the swim platform components have been adversely affected by water infiltration.

Call or email us for instructions for checking whether water may be present in your swim platform. These instructions are also available at your nearest Mainship dealer.

If it is determined that your swim platform is suffering from meaningful water infiltration, Mainship, at its expense, will correct the problem so that you may continue to enjoy your vessel, even though this condition does not prevent your use of the vessel.

Please contact us if you have any questions. Our number is (800) 578-0852 or you may wish to call me directly at (904) 827-2025.

Mike Hankins
(904) 827-2025
(800) 578-0852