



SERVICE BULLETIN 02-3902

Contact: Mike Hankins, Director of Customer Relations
Mainship Corporation
mhankins@mainship.com

November 21, 2002

Models Affected: 39 Trawler

Generator installed by factory with sound shield installed may have 110 volt fan on shield wired to 12 v wiring connection.

Any 39 Trawler with factory installed generator and sound shield, should be immediately checked for improper connection.

Any boats in the field that have the sound shield fan connected with the 12 volt current supply must make proper connections. Contact Customer Service for details.

Questions can be communicated to Mainship Engineering or Warranty/Service department.
Thanks for your assistance.

Mike Hankins
(904) 827-2025
(800) 578-0852